

EXECUTIVE SUMMARY

This report presents a summary of performance of operation, maintenance, and monitoring activities conducted at OU 3 Berman Pond Cap and Sodium Hydroxide Tank Cap systems and the remedial action at Building 514 over the last year.

There were no serious defects or issues identified during the annual inspection for either cap. All data has been loaded into the Microsoft Access CERCLA Cap System Database.

Compliance sampling at Building 514 has demonstrated attainment of cleanup goals, and no further action is planned for this site.

Planned activity for next year consists of continued compliance with the IOMP.